


Electrical Safety in the Workplace



FIPASS Workshop: Ref Incident Report ATLK-12-19-01 dated 03 December 2019

During a routine planned Monthly Workplace Inspection of the FIPASS Workshop on the North East Barge, an electrical hazard was identified and reported. This was subsequently tested by a qualified electrician and found to be live 240v cable, it was disconnect from the power source and removed.

Please be aware of electrical hazards in the workplace, in this case FIPASS and in particular around electrical installation points in Warehouses. If in doubt, do not touch any cable or electrically fed power point and report it to the FIPASS Duty Operations Manager straight away

{Original Signed}
Garry Ross
General Manager
Atlink Ltd