



**FIPASS HEALTH & SAFETY  
NOTICE  
Number 013  
Hot Works Restriction**

Atlink No.: ATLK-SN-013-V2

Issue Date: 08/03/18

Review Date: 07/05/18

**FIPASS HOT WORKS RESTRICTION**

Please be advised, additional safety measures following a serious incident on FIPASS Causeway, has been implemented with immediate effect. These temporary safety measures have been put in place to manage any potential risk.

These control measures will be in the form of the following;

1. No maintenance tasks to be conducted on the causeway legs, without prior approval of the Duty Operations Manager.
2. No Hot Works to be conducted within the Red Boxed area.
3. No causeway ballast tanks to be opened.

These temporary measures are with immediate effect and will remain in force until further written notice.




Figure 1: FIPASS Restricted Hot Works Area

Garry Ross  
General Manager  
Atlink Ltd